

Sondex Program Compatibility Matrix

21 April 2015

Warrior 8 Compatible Programs

Memlog	V3.xx	
Ultrawire Memlog	V3.xx	
Sondex Utilities	V9.xx	Requires a Sondex HASP key
WIPER	V3.xx	Requires a Sondex HASP key
WIVA	V4.xx	Requires a Sondex HASP key
MAPview	V2.xx	Requires a Sondex HASP key
MASware	V4.xx	Requires a Sondex HASP key
DECT Driver	V3.xx	
MULE Driver	V3.xx	
WEST	V2.xx	Requires a Sondex HASP key
Sondex USB Drivers	V3.x.x.x	
SDS USB Drivers	V4.x.x.x	

Warrior 7 Compatible Programs (V7.10 and releases from 2013.10.01)

Memlog	V2.6x	
Ultrawire Memlog	V2.6x	
Sondex Utilities	V8.xx	Requires a Sondex Hardlock key
WIPER	V2.x.x.x	Requires a Sondex Hardlock key
WIVA	V3.xx	Requires a Sondex Hardlock key
MAPview	V1.xx	Requires a Sondex Hardlock key
MASware	V3.xx	Requires a Sondex Hardlock key
DECT Driver	All	
MULE Driver	All	
WEST	V1.xx	Requires a Sondex Hardlock key
WEST	V2.xx	Requires a Sondex HASP key
Sondex USB Drivers	V3.x.x.x	
SDS USB Drivers	V4.x.x.x	



Warrior 7 Compatible Programs (V7.05 and releases up to 2013.9.30)

Memlog	V2.4x	
Ultrawire Memlog	V2.2x	
Sondex Utilities	V8.xx	Requires a Sondex Hardlock key
WIPER	V2.x.x.x	Requires a Sondex Hardlock key
WIVA	V3.xx	Requires a Sondex Hardlock key
MAPview	V1.xx	Requires a Sondex Hardlock key
MASware	V3.xx	Requires a Sondex Hardlock key
DECT Driver	All	
MULE Driver	All	
WEST	V1.xx	Requires a Sondex Hardlock key
WEST	V2.xx	Requires a Sondex HASP key
Sondex USB Drivers	V2.x.x.x	
SDS USB Drivers	V4.x.x.x	

Notes:

1. Warrior 8 is supported on both 32-bit and 64-bit operating systems.
2. Warrior 7 only works on 32-bit operating systems.
3. Later releases of Warrior 7 now use the same Sondex USB drivers as Warrior 8.
4. Users of Memlog and Ultrawire Memlog with Warrior 7 must install the correct versions as listed above as these programs use the same Sondex USB drivers as Warrior.
5. Warrior 8 users require updates to all existing Sondex programs as listed above.
6. Warrior 8 upgrades require new codes for existing Warrior 7 keys.
7. Protected Sondex programs for Warrior 8 require new physical keys.
8. DECT Driver V3.xx, MULE Driver V3.xx and WEST V2.xx are compatible with both Warrior 7 and Warrior 8.