

Next Generation MagneScan™ pipeline inspection tool

For assessing metal loss features, deformation and geometry,
plus advanced integrity assessments in oil and gas pipelines




years of operation
and growth



diameter range of
pipelines inspected so far

Designed to detect,
discriminate and size areas of
metal loss. Suitable for pinhole
corrosion and weld anomalies



of pipelines inspected
using this tool



Launched in
2009



1000
individual runs

560km



Longest single run

35 years

PII Pipeline Solutions
has been providing
pipeline integrity
services to the
global oil and gas
industry

Provides the data
needed to help you
manage your pipeline
assets safely and more
efficiently

